

VENTILATION AUDIT REPORT













SCHOOL:	Wamoon Public School (3364)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Leeton

3364 - Wamoon Public School
Site Plan (12018)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Duplicating Workroom - (11.28 SQM)	 Office (2)	
B00A - R0002 - Home Base - (43.49 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0003 - Home Base - (43.69 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R0004 - Staff Room - (11.21 SQM)	 Office (2)	
B00A - R0006 - Clerical Office - (10.87 SQM)	 Office (2)	
B00A - R0007 - Clerical Office/Workroom - (7.52 SQM)	 Office (1)	
B00A - R0008 - Entry Vestibule - (13.99 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (17.57 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Reading Area - (35.18 SQM)	 Student Space (16)	
B00C - R0003 - Staff Room - (23.32 SQM)	 Office (5)	
B00C - R0004 - Staff Kitchen - (5.19 SQM)	 Office (1)	
B00E - R0001 - Practical Activities - 1hb - (64.43 SQM)	 Student Space (29)	
B00E - R0002 - Practical Activities - 1hb - (26.39 SQM)	 Student Space (12)	
B00E - R0003 - Home Base - (64.36 SQM) - Teaching Space: 1	 Student Space (29)	