


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Warrumbungle National Park Environmental Ed Centre (5732)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Barwon</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Coonamble</b>

5732 - Warrumbungle National Park Environmental Ed Centre  
Site Plan (13336)





1:20,227

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0006 - Movement - (10.53 SQM)	Not Applicable	Circulation or storage space.
OS 522 10941 - OS 522 10941 - Staff Study - (38 SQM)	 Office (9)	
OS 531 10729 - OS 531 10729 - Library - (76 SQM)	 Student Space (35)	