


VENTILATION AUDIT REPORT

SCHOOL:	Waterfall Public School (3396)
AMU REGION:	Sydney
STATE ELECTORATE:	Heathcote
LOCAL GOVERNMENT AREA:	Sutherland

3396 - Waterfall Public School
Site Plan (13127)









1:467

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (68.42 SQM) - Teaching Space: 1	 Student Space (31)	
B00A - R0004 - Clerical Office/Workroom - (21.6 SQM)	 Office (5)	
B00A - R0005 - Reading Area - (38.4 SQM)	 Student Space (17)	
B00D - R0001 - Reading Area - (60.38 SQM)	 Student Space (28)	
NS 020 90197 - NS 020 90197 - Staff Study/Store - (38 SQM)	Not Applicable	Circulation or storage space.
OS 601 16364 - OS 601 16364 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	
OS 602 16300 - OS 602 16300 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	