


VENTILATION AUDIT REPORT

SCHOOL:	Wattle Flat Public School (3402)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Bathurst








3402 - Wattle Flat Public School
Site Plan (12896)



Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Communal Space - (88.22 SQM)	 Student Space (40)	
B00A - R0003 - Staff Room - (25.73 SQM)	 Office (6)	
B00A - R0004 - Practical Activities - 1hb - (18.54 SQM)	 Student Space (8)	
B00B - R0001 - Clerical Office - (15.73 SQM)	 Office (3)	
B00B - R0002 - Reading Area - (46.66 SQM)	 Student Space (21)	
B00B - R0003 - Movement - (6.43 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	
OS 603 12267 - OS 603 12267 - Learning Unit - Standard With P.A.A. A/C - (76 SQM)	 Student Space (35)	