


VENTILATION AUDIT REPORT

SCHOOL:	Weilmoringle Public School (4305)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Brewarrina

4305 - Weilmoringle Public School
Site Plan (12020)









1:806

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Staff Kitchen - (42.89 SQM)	 Office (10)	
B00A - R0004 - Principal - (43.5 SQM)	 Office (10)	
B00A - R1002 - Staff Room - (6.09 SQM)	 Office (1)	
B00A - R1007 - Home Base - (67.16 SQM) - Teaching Space: 1	 Student Space (31)	
B00A - R1008 - Home Base - (53.64 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0001 - Reading Area - (60.01 SQM)	 Student Space (27)	