


VENTILATION AUDIT REPORT

SCHOOL:	Wetlands Environmental Education Centre (5458)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Wallsend
LOCAL GOVERNMENT AREA:	Newcastle

5458 - Wetlands Environmental Education Centre
Site Plan (14662)









1:1,313

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0001 - Entry Vestibule - (31.22 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Clerical Office - (37.93 SQM)	 Office (9)	
B00B - R0003 - Staff Kitchen - (12.94 SQM)	 Office (3)	
B00B - R0005 - Sick Bay - (7.72 SQM)	 Student Space (3)	
B00C - R0001 - Communal Space - (112.94 SQM)	 Student Space (52)	
B00C - R0002 - Practical Activities - (98.57 SQM)	 Student Space (45)	
B00C - R0003 - Practical Activities - (98.13 SQM)	 Student Space (45)	
B00C - R0007 - Movement - (6.68 SQM)	Not Applicable	Circulation or storage space.
B00C - R0009 - Movement - (27.61 SQM)	Not Applicable	Circulation or storage space.