

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Whian Whian Public School (2980)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Lismore</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Lismore</b>






2980 - Whian Whian Public School  
Site Plan (13230)



Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Principal - (19.01 SQM)	 Office (4)	
B00A - R0003 - Withdrawal Space - 1hb - (23.36 SQM)	 Student Space (10)	
B00A - R0004 - Home Base - (38.44 SQM) - Teaching Space: 1	 Student Space (17)	
B00A - R0005 - Practical Activities - 1hb - (17.96 SQM)	 Student Space (8)	
B00A - R0007 - Movement - (34.86 SQM)	Not Applicable	Circulation or storage space.
B00G - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	