

VENTILATION AUDIT REPORT

SCHOOL:	White Cliffs Public School (3435)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Central Darling

3435 - White Cliffs Public School
Site Plan (11809)



1:510

Printed: 18-Aug-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (59.33 SQM) - Teaching Space: 1	● Student Space (27)	
B00A - R0005 - Movement - (66.36 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Reading Area - (51.16 SQM)	● Student Space (23)	
B00B - R0002 - Clerical Office - (33 SQM)	● Office (8)	
B00D - R0001 - Home Base - (59.97 SQM) - Teaching Space: 1	● Student Space (27)	