
VENTILATION AUDIT REPORT



SCHOOL:	Woolomin Public School (3506)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Room - (13.68 SQM)	Office (3)	
B00A - R0002 - Home Base - (37.79 SQM) - Teaching Space: 1	Student Space (17)	
B00A - R0003 - Principal - (8.87 SQM)	Office (2)	
B00A - R0004 - Clerical Office - (11.58 SQM)	Office (2)	
B00B - R0001 - Home Base - (59.39 SQM) - Teaching Space: 1	Student Space (27)	
B00B - R0002 - Movement - (15.65 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Reading Area - (41.46 SQM)	Student Space (19)	
B00C - R0002 - Entry Vestibule - (10.72 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Clerical Office/Workroom - (19.09 SQM)	Office (4)	
B00C - R0004 - Staff Kitchen - (7.2 SQM)	Office (1)	
B00C - R0007 - Principal - (12.98 SQM)	Office (3)	
B00C - R0009 - Movement - (5.9 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	