
VENTILATION AUDIT REPORT



SCHOOL:	Wyong Creek Public School (3528)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Wyong
LOCAL GOVERNMENT AREA:	Central Coast



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Clerical Office - (14.47 SQM)	Office (3)	
B00A - R0004 - Sick Bay - (10.62 SQM)	Student Space (4)	
B00A - R0005 - Principal - (10.68 SQM)	Office (2)	
B00A - R0006 - Staff Room - (16.32 SQM)	Office (4)	
B00A - R0008 - Movement - (5.08 SQM)	Not Applicable	Circulation or storage space.
B00A - R0010 - Staff Room - (23.58 SQM)	Office (5)	
B00A - R0011 - Staff Kitchen - (10.46 SQM)	Office (2)	
B00C - R0001 - Practical Activities - 1hb - (20 SQM)	Student Space (9)	
B00D - R0002 - Practical Activities - 1hb - (8.63 SQM)	Student Space (4)	
B00D - R0003 - Home Base - (51.46 SQM) - Teaching Space: 1	Student Space (23)	
B00D - R0004 - Movement - (16.01 SQM)	Not Applicable	Circulation or storage space.
B00I - R0001 - Reading Area - (60.72 SQM)	Student Space (28)	
OS 601 13504 - OS 601 13504 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 602 10459 - OS 602 10459 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	
OS 602 15480 - OS 602 15480 - Learning Unit - Standard With P.A.A (76 SQM)	Student Space (35)	