

VENTILATION AUDIT REPORT

SCHOOL:	Wyrallah Public School (3529)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Lismore

3529 - Wyrallah Public School
Site Plan (11415)



1:527

Printed: 13-Jan-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (26.22 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Entry Vestibule - (18.28 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Movement - (5.38 SQM)	Not Applicable	Circulation or storage space.
B00A - R0007 - Duplicating Workroom - (10.56 SQM)	Office (2)	
B00A - R0010 - Staff Kitchen - (10.43 SQM)	Office (2)	
B00A - R0011 - Clerical Office/Workroom - (13.88 SQM)	Office (3)	
B00A - R0012 - Staff Room Annexe - (17.85 SQM)	Office (4)	
B00A - R0013 - Principal - (14.3 SQM)	Office (3)	
B00A - R0014 - Movement - (5.04 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Reading Area - (52.18 SQM)	Student Space (24)	
B00B - R0004 - Staff Room - (16.54 SQM)	Office (4)	
B00C - R0001 - Movement - (20.36 SQM)	Not Applicable	Circulation or storage space.
B00D - R0006 - Movement - (12.28 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (12.38 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	Student Space (27)	
OS 602 10131 - OS 602 10131 - Learning Unit - Standard With P.A.A. - (76 SQM)	Student Space (35)	