
VENTILATION AUDIT REPORT



SCHOOL:	Yanco Public School (3536)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Leeton



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (47.7 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0004 - Home Base - (47.69 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0005 - Home Base - (47.82 SQM) - Teaching Space: 1	Student Space (22)	
B00A - R0009 - Practical Activities - 1hb - (5.63 SQM)	Student Space (2)	
B00A - R0011 - Home Base - (66.11 SQM) - Teaching Space: 1	Student Space (30)	
B00A - R0013 - Movement - (14.85 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Duplicating Workroom - (8.52 SQM)	Office (2)	
B00B - R0003 - Clerical Office - (14.82 SQM)	Office (3)	
B00B - R0005 - Entry Vestibule - (18.27 SQM)	Not Applicable	Circulation or storage space.
B00B - R0006 - Principal - (12.53 SQM)	Office (3)	
B00B - R0007 - Staff Room - (24.93 SQM)	Office (6)	
B00B - R0008 - Clerical Office/Workroom - (10.36 SQM)	Office (2)	
B00B - R0010 - Reading Area - (72.51 SQM)	Student Space (33)	
B00C - R0001 - Movement - (5.23 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Home Base - (53.96 SQM) - Teaching Space: 1	Student Space (25)	
B00D - R0002 - Canteen - (38.16 SQM)	Not Applicable	Circulation or storage space.