

VENTILATION AUDIT REPORT

SCHOOL:	Yarrowitch Public School (3547)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Walcha

3547 - Yarrowitch Public School
Site Plan (11476)








1:754

Printed: 21-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (46.24 SQM)	 Student Space (21)	
B00A - R0003 - Home Base - (54.33 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0005 - Principal - (13.48 SQM)	 Office (3)	
B00A - R0006 - Movement - (12.8 SQM)	Not Applicable	Circulation or storage space.
B00A - R0009 - Principal - (17.7 SQM)	 Office (4)	
B00C - R0001 - Movement - (26.58 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Reading Area - (61.39 SQM)	 Student Space (28)	