

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Yerong Creek Public School (3556)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Wagga Wagga</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Lockhart</b>

3556 - Yerong Creek Public School  
Site Plan (11480)










1:630

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (55.47 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0005 - Home Base - (55.64 SQM) - Teaching Space: 1	 Student Space (25)	
B00A - R0006 - Home Base - (56.33 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0008 - Clerical Office - (12.5 SQM)	 Office (3)	
B00A - R0012 - Principal - (13.67 SQM)	 Office (3)	
B00A - R0013 - Staff Room - (15.55 SQM)	 Office (3)	
B00A - R0015 - Entry Vestibule - (7.42 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (65.4 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	