

Blakebrook Public School

Works notification | 21 July 2026

Dear parents, staff and carers,

We would like to provide you with an update on the works notifications sent on [Tuesday 24 February 2026](#) regarding the drinking water quality test results for Blakebrook Public School.

We are pleased to inform you that work has now been finished by a qualified and accredited contractor.

The following water supply outlets were then re-tested by an independent hygienist:

- the bubblers upstairs near the canteen
- the bubblers in the undercroft area on the ground floor of the Administration Building
- handbasin in the access toilet on the first floor in the Administration Building
- sink in the practical activities area in Building M.

The results confirm that the water quality now meets the requirements of the [Australian Drinking Water Guidelines](#).

Access to the water supply outlets at the bubblers and tap have been restored and can now be used by students and staff.

If you have any questions about this process, please contact the NSW Department of Education.

Thank you for your understanding and support during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
schoolinfrastructure.nsw.gov.au