

Blakebrook Public School

Works notification | 27 June 2024

Dear staff, parents and carers,

Drinking water quality testing was recently conducted at Blakebrook Public School (currently situated at the site of Goolmangar Public School) as part of our routine water testing program.

Findings have detected bacteria in samples collected from the tap outlets at the following locations:

- staff room in Building B
- outside the demountable classroom
- practical activities area in Building E
- staff kitchen and sick bay.

As a precautionary safety measure, access has been restricted to the tap and we are working with an independent hygienist to undertake any remediation work required.

All work will be carried out by qualified contractors, and we will undertake additional testing at the school following the work to ensure the water can continue to be used.

The health, safety and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au