

Carlton South Public School

Works notification | 22 September 2025

Dear staff, parents, carers and neighbours,

On Thursday 18 September 2025, fragments assumed to contain bonded asbestos were identified on the western side of the grounds at Carlton South Public School.

As a precaution, the area, which was already out of bounds, was immediately taped off from students and staff and a hygienist was engaged to provide advice.

NSW Health explains that “living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged”.

The fragments are believed to have surfaced due to recent wet weather. The location is not in the school’s asbestos register, which will be updated to include this find.

Removal of all fragments from the site will take place outside of school hours between Monday 22 and Wednesday 24 September 2025.

All work will be done in accordance with work health and safety laws and the NSW Department of Education’s Asbestos Management Plan.

Safety measures will be in place while work is being done. All work will be completed by licensed asbestos contractors and inspected by independent hygienists who will provide a clearance certificate when work is finished.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au