

Peak Hill Central School

Works notification | 17 September 2026

Dear staff, parents and carers,

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

During scheduled maintenance, a contractor replaced lights attached to ceiling sheets in a classroom in the demountable building on the southern side of Building B. The ceiling sheets are known to contain asbestos, as identified in the school's Asbestos Management Plan.

The demountable building was isolated as a precaution, and an independent hygienist was engaged on **8 September 2026** to inspect the area and provide recommendations for any necessary works required. Following the inspection, the hygienist recommended, as a further precautionary measure, an **environmental clean of the interior of the demountable**.

The environmental clean was **completed outside of school hours on Monday 14 September 2026**. The work was undertaken under the supervision of the independent hygienist, with **air monitoring in place throughout the necessary works**.

The independent hygienist has confirmed that the area can be reopened for usual school activities.

All work has been undertaken in accordance with work health and safety requirements and the NSW Department of Education's Asbestos Management Plan. Appropriate safety measures have been in place throughout the works, with the remediation supervised by an independent hygienist.

We thank staff, students, parents, carers and the wider school community for their understanding and cooperation while these precautionary measures have been undertaken.

If you have any questions about this work, please contact the NSW Department of Education using the details below.

Thank you for your continued understanding and support.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au