

Dear staff, parents and carers,

Drinking water quality testing was recently conducted at Tregeagle Public School as part of our routine water testing program.

Findings have detected bacteria in samples collected from the following locations:

- north side bubblers located at Building A,
- tap outlet located in the walkway of Building D,
- bathroom sink tap and exterior tap outlet located at Building F,
- sink tap located in the Practical Activities Area of Building I, and
- the staff room tap.

As a precautionary safety measure, access has been restricted to the tap outlets and we are working with an independent hygienist to undertake any remediation work required.

All work will be carried out by qualified contractors, and we will undertake additional testing at the school following the work to ensure the water is safe for use. We will provide an update once we have confirmation of the details of this work.

The health, safety and wellbeing of the school and the local community is our highest priority.

If you have any questions about this work, please contact the NSW Department of Education on the details below.

Thank you for your cooperation during this important work.

School Infrastructure

Email: schoolinfrastructure@det.nsw.edu.au

Phone: 1300 482 651

www.schoolinfrastructure.nsw.gov.au