

Tregeagle Public School

Works notification | 20 August 2024

Dear staff, parents and carers,

Further to the [Works Notification on 19 June](#) regarding the drinking water quality test results for Tregeagle Public School, remediation work has been completed by a qualified and accredited tradesperson following advice by an independent hygienist.

Re-testing of the affected tap outlets by an independent hygienist has returned results that meet the requirements of the [Australian Drinking Water Guidelines](#).

Access to the tap outlets in the following locations has been restored and can be used again by students and staff:

- tap outlet located in the walkway of Building D
- bathroom sink tap and exterior tap outlet located at Building F
- sink tap located in the Practical Activities Area of Building I
- the tap located in the staff room demountable.

The tap outlet at the wash trough on the north side of Building A requires additional work before access can be restored. This is due to the sample not meeting the requirements of the [Australian Drinking Water Guidelines](#) after the initial cleaning, disinfection, and re-testing.

Please note, the wash trough on the north side of Building A was incorrectly listed as north side bubblers located at Building A in the Works Notification on 19 June.

The health and wellbeing of students, staff and the local community is our highest priority.

We will keep the community updated.

Thank you for your cooperation during this important work.

