

Hamilton South Public School

Works notification | 4 April 2024

Dear staff and parents/carers,

As part of planned work, we are removing a rotted beam and roof tiles in the undercover walkway between Building E and the student toilets (Building G) at Hamilton South Public School. This work will involve working with bonded asbestos-containing material in the roof cavity, as listed on the school's asbestos register.

NSW Health explains that if bonded asbestos is mixed with cement or other hard bonding materials, and in good condition, it is likely to be low-risk.

Work to remove the asbestos containing material will take place outside of school hours on Saturday 6 April 2024.

The movement area will be cordoned off before the work starts, and safety measures and monitoring put in place.

All work will be done in accordance with work, health and safety laws and the NSW Department of Education's Asbestos Management Plan. All work will be completed by licensed and accredited asbestos contractors and monitored by independent hygienists in strict accordance with all applicable legislation, regulations, policies, and guidelines.

The movement area will be inspected by the independent hygienist to confirm it has been fully remediated, and the school will receive a clearance certificate before the movement area is reopened.

The health, safety, and wellbeing of the school and the local community is our highest priority.

Thank you for your cooperation during this important work.

