

Kandos High School

Works notification | 13 May 2025

Dear staff, parents and carers,

During a routine maintenance inspection on Monday 10 February 2025, a staff member found a broken fragment of suspected asbestos containing material in the electrical distribution box located in Building A at Kandos High School. This box is out of bounds to students.

The box was immediately closed, padlocked and signs put up to prevent staff access. This box is known to contain bonded asbestos as listed on the school's asbestos register.

On Thursday 13 February 2025, licensed contractors removed the asbestos material from the electrical distribution box and sealed to enclose the damage.

All work was done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures, including air monitoring were in place while work was being done. All work was completed by licensed asbestos contractors and inspected by independent hygienists.

Once the works were completed, an independent hygienist inspected the area and issued a clearance certificate.

The box will continue to remain out of bounds to students.

The health, safety, and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au