

Castle Hill High School

Works notification | 6 June 2025

Dear staff, parents and carers,

During a proactive inspection, we have identified a door in the multipurpose building at Castle Hill High School in poor condition.

The door has been taped up and will be removed Saturday 7 June 2025, with air monitoring in place while work is being done.

The door lining contains bonded asbestos material, which was common building practice in the time it was built, as indicated in the school's asbestos register.

NSW Health explains that "living or working with asbestos, or just being around it, is a low risk to your health as long as the asbestos is in good condition and not damaged".

All work involving asbestos-containing materials will take place outside of school hours.

All work will be done in accordance with work health and safety laws and the NSW Department of Education's Asbestos Management Plan. Safety measures will be in place while work is being done.

All work will be completed by licensed asbestos contractors and inspected by independent hygienists to confirm it has been fully remediated, and a clearance certificate will be issued before the area can continue to be accessed.

The health, safety and wellbeing of all members of our school and the local community are our highest priorities.

Thank you for your cooperation during this important work.



Email: schoolinfrastructure@det.nsw.edu.au
Phone: 1300 482 651
www.schoolinfrastructure.nsw.gov.au

