


SCHOOL:	Barwon Learning Centre (5762)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Moree Plains











5762 - Barwon Learning Centre
Site Plan (13031)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0001 - Home Base - (58.33 SQM) - Teaching Space: 1	 Student Space (349)	
B00B - R0006 - Home Base - (58.23 SQM) - Teaching Space: 1	 Student Space (349)	
B00B - R0009 - Home Base - (57.09 SQM) - Teaching Space: 1	 Student Space (325)	
B00E - R0001 - Entry Vestibule - (12 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Interview - (12.89 SQM)	 Office (3)	
B00E - R0003 - Principal - (12.78 SQM)	 Office (3)	
B00E - R0004 - Movement - (21.1 SQM)	Not Applicable	Circulation or storage space.
B00E - R0005 - Clerical Office - (17.52 SQM)	 Office (4)	
B00E - R0006 - Sick Bay - (6.61 SQM)	 Student Space (3)	
B00E - R0011 - Staff Kitchen - (22.6 SQM)	 Office (5)	
B00E - R0012 - Staff Room Annexe - (13.88 SQM)	 Office (3)	
B00G - R0002 - Reading Area - (61.53 SQM)	 Student Space (28)	