


# VENTILATION AUDIT REPORT Version 2



<b>SCHOOL:</b>	<b>Carool Public School (1515)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Tweed</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Tweed</b>







1515 - Carool Public School  
Site Plan (12226)



Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (13.94 SQM)	 Office (3)	
B00A - R0002 - Duplicating Workroom - (10.26 SQM)	 Office (2)	
B00A - R0003 - Home Base - (53.21 SQM) - Teaching Space: 1	 Student Space (40)	
B00A - R0004 - Principal - (11.67 SQM)	 Office (2)	
B00A - R0005 - Staff Room - (7.94 SQM)	 Office (1)	
B00B - R0001 - Reading Area - (20.18 SQM)	 Student Space (9)	