


# VENTILATION AUDIT REPORT Version 2

<b>SCHOOL:</b>	<b>Corndale Public School (1656)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Lismore</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Lismore</b>










1656 - Corndale Public School  
Site Plan (11958)



Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Home Base - (43.62 SQM) - Teaching Space: 1	 Student Space (33)	
B00A - R0004 - Reading Area - (43.17 SQM)	 Student Space (20)	
B00A - R0005 - Staff Room - (11.03 SQM)	 Office (2)	
B00A - R0009 - Entry Vestibule - (16.07 SQM)	Not Applicable	Circulation or storage space.
B00A - R0010 - Movement - (14.07 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Principal - (13.26 SQM)	 Office (3)	
B00B - R0001 - Canteen - (13.81 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Interview - (14.45 SQM)	 Office (3)	
B00D - R0002 - Interview - (13.3 SQM)	 Office (3)	
B00D - R0007 - Movement - (8.74 SQM)	Not Applicable	Circulation or storage space.
B00D - R0012 - Interview - (14.41 SQM)	 Office (3)	
B00D - R0013 - Withdrawal Space - 1hb - (23.66 SQM)	 Student Space (10)	
B00D - R0017 - Staff Kitchen - (11.2 SQM)	 Office (2)	