


VENTILATION AUDIT REPORT Version 2

SCHOOL:	Glen Alice Public School (3903)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Lithgow





3903 - Glen Alice Public School
Site Plan (12732)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Principal - (14.47 SQM)	 Office (3)	
B00A - R0004 - Home Base - (52.21 SQM) - Teaching Space: 1	 Student Space (38)	
B00A - R0008 - Clerical Office - (17.51 SQM)	 Office (4)	
B00B - R0001 - Special Programs Room - (20.91 SQM)	 Student Space (9)	